



Ribbfillen

The number 1 for a gas-tight storage room!

Are your cold rooms no longer completely gastight? Or are your cold rooms in need of renovation? We are happy to put our knowledge and experience to work for you.

With the right primer for good adhesion, a reinforcing fleece, a multi-layer technique and a high-quality coating, we can ensure long-term gastightness for you.

ribbstyle.com



Testing

Does the nitrogen generator turn on regularly? That means the oxygen level in your cold room is too high. Time to test your ULO room.



New construction

Are you planning to build new cold stores? Make sure to get the right treatment from the start. We can help you!



Renovation

Does testing reveal that your rooms need renovation? Contact us. For years, we have had the perfect solution: "RibbFillen" of the seams.



Constant water load

Do you have a constant water load in your cold rooms? If so, we recommend applying an additional topcoat to the wall/floor joint. Please inquire about the possibilities.



Check our website for product information

Our options

- Repainting existing joints
- Repainting soiled surfaces

RibbStyle

RibbFill Control Coat

- Applying floor systems
- · Repairing floor cracks
- Installing floor lines
- Repairing thresholds
- Treating seams
- Testing rooms



Interested in our gastight coating?

You can reach us at phone number (+31) 113 622 533 or by email at info@ribbstyle.com.

ProFill Protect MS